

## **Operations Summary**

#### Starting back up out of the shutdown period

Store	Start	Duration (hr)	Init. Lum (E30)	Del. (nb <sup>-1</sup> )	Live (nb <sup>-1</sup> )	Eff (%)	Comments
2194	02/10	.7	e27(4.5)	-	-	-	Clock sync problem, Quench – Abort Kicker
2208	02/11	3	17.3	167.5	69.6	42	Min_bias trigger for clc calib. Tested rol trigger table, Quench – QPM card
	02/12	Controlled Access					
2213	02/13	>7	20	437	383	87	Running pre-shutdown TT, started slow, but stable



#### **Stores on Mon & Tues**

#### **Store 2194**

- Reported Lumi e27 due to TeVatron beam sync delay that was off by 1.9us.
  - mistakenly reset by MCR to 0 sometime during Sup. Access.
  - This delay will be checked as part of the shot setup checklist.
- Ended with a quench- possibly due to an abort kicker prefire.

#### **Store 2208**

- Lumi = 17.3 e30
- MINIMUM\_BIAS\_1[9,251,318]
  - for CLC calibration.
- PHYSICS\_1\_03[2,214,329]
  - Read Out Lists tested
- Data taking hiccups...
  - Persistent L2 DTOs held off initial running. Iso Clique problem.
  - Several COT SL7 trips.
- Store ended with a quench
  - (QPM: UPS card at A2 died).



# Controlled Access Wednesday 2/12

- Beams Div. had jobs that required access
  - Investigate beam pipe vacuum at F sector.
- Address DTO's from smx cards
  - ccal06 slot 3: power cycled and swapped card.
  - ccal07 slot 4: power cycled crate.
  - No problems in today's store.
- Fixed fans in SMD-SE 9 & 11 faulty plug-in.
- Investigated a flaky trigger output b0pcal11(slot 19)
  - Mismatch in DCAS trigger tower and admem Et. Not fixed.
- Upstairs during the QT...
  - Investigated/fixed bookkeeping problem between calib DB and admem FRAMS.
  - Rebooted clc crate to pick up new calibrations.



## Today's Store Thursday 02/13

- Store 2213 running smoothly
  - $\sim 87\%$  efficiency, Initial Lum = 20e30.
- Running pre-shutdown trigger table.
- At start of store:
  - IFIX responding slowly:
    - Maybe due to errant priority settings for virus scan that occurred in IFIX nodes at 4am(just as store went in).
      - Virus scanning server at fcc upgraded from NT -> 2000
    - Mixed versions (still need to update clc, plug, and SVX)
  - CMP trips
- COT SL7 off.





### **Activities this past week**

- Torture DAQ
  - L2 torture testing (40Khz @ L1, 300Hz @ L2)
- Read Out List testing new firmware in TS partitions
- SVT timing scans
  - Investigate (dead)time to propagate Si data after L1 accept to SVT
- New Tof trigger working. Triggered on cosmics...
- Plug sourcing.
- ISL Cooling flow alarm problem fixed bug in code…
- Updating to 3.0 IFIX (still need to do SVX, Plug, and CLC)



## **TOF Cosmic trigger**







### **Outstanding Issues**

#### COT SL7 is Off

- Problem with current draw on a full cell. Trips w/beam.
- PS's need to be reconfigured to limit this to 1 quadrant.
- Stereo Layer.
- Requires ~12 hour access to fix swap a daughter card at the COT face to disable the cell.
- Immediate plan is to fix this at the earliest opportunity and to better understand the effect on tracking.
  - Chris Hays is looking into this



## Outstanding Issues continued...

- Integrate Silicon into stores
  - Immediate plan is to see how this store ends. If it ends in a controlled manner, integrate Si in the next store.
- Fix calorimeter trigger tower issue.
  - Carla and Vivek are working on it.
- Iso Clique problem that requires power cycling b0l2cl00.
  - L2 decision time outs not fixed by HRR.
- B0cot04 byte shift error has shown up again...
- Monitoring cmx and cmp blue beam currents during stores.